

GeoCHEM FOAMER

Concentrated Foam Marker

A blend of specialty surfactants and other additives designed to produce thick long lasting foam. It will work over a range of water hardness to produce a thick long lasting foam.

Application Guidelines

Rate of use: Foamer can be used at varying rates, depending upon the desired consistency of foam.

For firmer foams use at 1 part Foamer to 80 parts water For normal foams use at 1 part Foamer to 100 partsWater.

The air pressure may need to be adjusted to produce a thick, fine bubble foam. If the foam produced is too sloppy, increase the level of Foamer and /or the level of air.

It is best applied in large blobs to the ground surface to give the most visual effect.



Sales & Procurement Center - Phone No. 907.562.5755 ~ Fax No. 206.219.3740

WA State Sales - Phone No. 206.774.8777 ~ Toll Free: 800.490.5320

GeoCHEM Website: http://www.geocheminc.com/contactus.php